

SAP QM MODULE TRANSACTION CODES LIST

1. QM01 : Tcode for Create quality notification
2. QM02 : Tcode for Change quality notification
3. QM03 : Tcode for Display quality notification
4. QM10 : Tcode for Change list of quality notifications
5. MCOM : Tcode for QMIS: Customer Analysis Level/Disp.
6. IQS22 : Tcode for Process Notif. : Tcode for Simplified View
7. QM11 : Tcode for Display List of Qual. Notifications
8. IQS1 : Tcode for Create Notification : Tcode for Extended View
9. IQS2 : Tcode for Change Notification : Tcode for Extended View
10. QM12 : Tcode for Change list of tasks
11. QM15 : Tcode for Display list of items
12. IQS8 : Tcode for Worklist: Notifications (General)
13. IQS21 : Tcode for Create Notif. : Tcode for Simplified View
14. QM13 : Tcode for Display list of tasks
15. IQS3 : Tcode for Display Notification : Tcode for Extended View
16. QA11 : Tcode for Record usage decision
17. QA02 : Tcode for Change Inspection Lot
18. QE51N : Tcode for Results Recording Worklist
19. QA12 : Tcode for Change usage decision with history
20. QA01 : Tcode for Create Inspection Lot
21. QA16 : Tcode for Collective UD for accepted lots
22. QE01 : Tcode for Record characteristic results
23. QA08 : Tcode for Collective Processing of Insp. Setup
24. QA03 : Tcode for Display inspection lot
25. QAC2 : Tcode for Transfer stock to insp. lot
26. QAC3 : Tcode for Reset sample
27. QE11 : Tcode for Record results for inspection point
28. QE51 : Tcode for Results recording worklist
29. QE71 : Tcode for Tabular res. recording for insp. pts

30. QVM2 : Tcode for Inspection lots with open quantities
31. QA32 : Tcode for Change data for inspection lot
32. QA11 : Tcode for Record usage decision
33. MCODE : Tcode for QMIS: Quantitative Results for Cust.
34. QP01 : Tcode for Create
35. QA02 : Tcode for Change Inspection Lot
36. QM01 : Tcode for Create quality notification
37. QM02 : Tcode for Change quality notification
38. QE51N : Tcode for Results Recording Worklist
39. QA07 : Tcode for Trigger for recurring inspection
40. QA12 : Tcode for Change usage decision with history
41. QS41 : Tcode for Maintain catalog
42. QA01 : Tcode for Create Inspection Lot
43. QS21 : Tcode for Create master insp. characteristic
44. QA33 : Tcode for Display data for inspection lot
45. QP02 : Tcode for Change
46. IH01 : Tcode for Functional Location Structure
47. IL02 : Tcode for Change Functional Location
48. IL01 : Tcode for Create Functional Location
49. I009 : Tcode for Location/AccAsst No. Range (ILOA)
50. IH06 : Tcode for Display Functional Location
51. IL03 : Tcode for Display Functional Location
52. IH09 : Tcode for Display Material
53. IH03 : Tcode for Equipment Structure
54. IL06 : Tcode for Data Transfer From FunctLocation
55. IL05 : Tcode for Change Functional Location
56. IH05 : Tcode for Material Structure
57. IH04 : Tcode for Equipment Structure
58. IL04 : Tcode for Create FunctLocation: List Entry
59. IH07 : Tcode for Display Reference Location
60. IL11 : Tcode for Create Reference Location

61. QC20 : Tcode for Certificates for Deliveries
62. QC21 : Tcode for Quality certificate for the insp.lot
63. QC01 : Tcode for Create certificate profile
64. QC51 : Tcode for Create certificate in procurement
65. QC22 : Tcode for Quality Certificate for Batch
66. QC15 : Tcode for Create cert. profile assignment
67. QC02 : Tcode for Change certificate profile
68. QC55 : Tcode for Worklist: Certificates : Tcode for Procurement
69. QC03 : Tcode for Display certificate profile
70. QC17 : Tcode for Display cert. profile assignment
71. QC53 : Tcode for Display certificate in procurement
72. QC52 : Tcode for Change certificate in procurement
73. QC11 : Tcode for Create cert. profile assignment
74. QC16 : Tcode for Change cert. profile assignment
75. QC32 : Tcode for Archive display: Inspection lot

QM Tutorial: <http://sapbrainsonline.com/qm-tutorial>